

Accuracy. Closeness of a measure to true value; sample mean close to true mean (cf. bias).

Precision. Repeatability of a measure; low sample variance (cf. variability).